



SAFETY SYSTEM®
YOUR PROTECTOR

Sir Safety System S.p.A. Single-member company
Wholly-owned subsidiary of Sir Holding Srl
Via dei Fornaciai, 9 - Santa Maria degli Angeli
06081 Assisi - Perugia - Italy
Tel.+39 075.8043737 - Fax +39 075.8048686

VAT Nr. IT 03359340548
Viale Europa 74
20090 Cusago Milano
Tel. +39 02.90394575
Fax +39 02.90394441

TECHNICAL SHEET

export@sirsafety.com
www.sirsafety.com



UNI EN ISO 9001:2015
UNI EN ISO 14001:2015
UNI EN ISO 45001:2018

Name: POLYTECH Padded trousers	Code: MC576102	MC57 CLOTHING - POLYTECH SERIES
---------------------------------------	-----------------------	--

Description

Trousers made of a technical fabric composed by 75% cotton, 24% polyester, 1% antistatic fibre fabric, weight 280 g/m , padding 100% aramid fibre 205 g/m , lining 50% aramid fibre 130 gr/m . It features a fly with zip and button, two front pockets with flap and Velcro, rear pocket with flap and Velcro, two three-dimensional functional pockets with flaps and Velcro on the legs. Featuring knee pad pockets.

THE TROUSERS SHALL BE WORN IN COMBINATION WITH THE JACKET

- The Polytech series is made with a multi-purpose fabric that combines antistatic properties with resistance to flames, heat and chemical products.
- Thanks to its features it is multi-purpose, practical and resistant, breathable and comfortable.

The product has been designed and manufactured to comply with Regulation (EU) 2016/425.

In combination with the coverall, is it possible to wear our under garments: Carboflame undershirt art. MC5610 and Carboflame underpants art. MC5620.



Category III	Colours TWO-TONE	Available Sizes Made to order: 40 - 70 In stock:
------------------------	----------------------------	--

Quantity/Carton 5	EC Standards	Important Information Petrochemical Industry, Metalworking Industry, Refining Industry, Chemical Industry, Industrial Maintenance and Assemblies, Gas, Water and Electricity Mains Maintenance and Management, Oil & Gas industry. Keep in a cool dry place, far from heat sources and direct light. Make sure the garment is in good condition, undamaged and clean before use. Once you become aware of a damage, you should immediately replace it. Keep in a cool dry place, far from heat sources and direct light. Make sure the garment is in good condition, undamaged and clean before use. Once you become aware of a damage, you should immediately replace it.
-----------------------------	--------------	---

Dexterity

Storage and cleaning